

PHOTOGRAPHIC RECORD – Site Audit Visit, 26 May 2023, Conducted by Dr Vanessa Weyer



Image 1:
Rehabilitated dune vegetation showing good coverage, view to the north-east.



Image 2:
Rehabilitated dune vegetation showing good coverage, view to the south-west.



Image 3:
Close up view of successfully established dune plant species.



Image 4:
Cut brush used as natural fencing for wind and sand protection, to encourage dune rehabilitation, still in place and functional.



Image 5:
Stormwater outfalls between housing require attention, to mitigate against soil erosion - as part of the ongoing Maintenance Management Plan



Image 6:
Footings under step entrances from houses require attention - as part of the ongoing Maintenance Management Plan



Image 7:
Some scour has occurred along the stream edge, east section of site. This is to be expected and will be ongoing, to be monitored and repaired as part of the Maintenance Management Plan.




Image 8:
View of stream flow. Note ramp to the right of the stream has been rehabilitated.



Image 9:
Construction vehicle access between houses has recovered well and is showing good rehabilitation results.



Image 10:
Well established plant material.



Image 11:
Dune vegetation establishment has been aided by water from irrigation sprinklers



Image 12:
View across the stream looking towards the west, towards the site